

Scenix Mixing Guide



Scenix Mural & Theme Paint Scenix High Performance

ACTIVATED – FAST CURE

Cures in 4-6 hours / Tape and Clear in 1 hour

STEP 1	Additive	4016 Cross-Linker	<ul style="list-style-type: none">• Add 2% per volume• Mix thoroughly
STEP 2	Dilutant	4012	<ul style="list-style-type: none">• Add 2-10% per volume• Mix thoroughly & wait 10 minutes to acclimate before using• 4-hour pot-life after thinning with 4012 [or 4011]

NON-ACTIVATED

Cures in 48 hours / Tape and Clear in 4-8 hours

STEP 1	Dilutant	4014	<ul style="list-style-type: none">• Activating with 4016 Cross-Linker not required when thinning with 4014• Add 5-10% per volume• Mix thoroughly & wait 10 minutes to acclimate before using• 45-60 minute pot-life after thinning with 4014
--------	----------	------	---

SSR Clear [Sun Screen Resistant]

STEP 1	Additive	4015 Cross-Linker	<ul style="list-style-type: none">• Add 2% per volume• Mix thoroughly
STEP 2	Dilutant	4011	<ul style="list-style-type: none">• Add 2-10% per volume• Mix thoroughly & wait 10 minutes to acclimate before using• 4-hour pot-life after thinning with 4011

FLEXIBLE SUBSTRATES:

Activate SSR Clear with 4016 Cross-Linker added 2% per volume, then thin with 4011 Diluant.



PO Box 120, 14 Airport Park Rd | East Granby, CT 06026
800.243.2712 | 860.653.5505 | createxcolors.com

Available from:
Dixie Art Airbrush
www.dixieart.com
800-783-2612 - 504-836-0069

020219