



## Technical Data Sheet

### Scenix SSR Clears (Sun Screen Resistant)

7030 SSR Gloss, 7031 SSR Matte, 7032 SSR Satin

Water-Base

Low VOC (30.43 g/L Act.; 129 g/L Reg.)

Aliphatic Acrylic-Urethane

ASTM E84 Class A Fire Rating Smoke & Flame Spread

Brush, Roll or Spray Application



Made in U.S.A.

#### Scenix SSR Set-Up & Mix

- Add 2oz. 4015 Cross-Linker to 1-Gallon Scenix SSR Clear.
- After activating with 4015, reduce Scenix:
  - 7030 SSR Gloss Clear: 2 – 10% per total volume with 4011 to maintain maximum sheen. 4011 is design for all gloss applications.
  - 7031 SSR Matte & 7032 SSR Satin Clears: 2 – 10% per volume 4012.
- Stir in reducer, do not shake on agitator.
- Allow SSR Clear mix ~ 10 minutes to acclimate, then spray.

#### Scenix SSR Application

- Apply tack coat. Subsequent coats medium-wet.
- 3 – 4 coats should be applied for pinhole-free coverage.
- Do not allow material to dry spray as this may create adhesion failure. Too much distance at high pressure creates a dry spray.
- Any milkiness from over-application will dry water-clear.

#### Equipment Size & Set-Up

Spray gun: 1.2 – 1.4mm tip-size ~ 22 – 24 psi

Mini-Gun: 1.2mm tip ~ 22 – 24 psi

Brush: Use quality brush made for water-based paint.

Roller: Keep wetted edge

#### Drying Times

At 70 degrees F and 65% Relative Humidity, Scenix will dry to a matte coat in approximately 5 – 10 minutes.

- Use air to assist curing and shorten drying times. Avoid direct heat to force dry Scenix.
- Use of direct heat to dry Scenix will cause a loss of adhesion due to plasticizing of paint surface.
- Allow a 1-hour cure time minimum before top-coating with clear.

#### Humid & Cold Conditions

- Replace 4012 and thin with 4020.
- Allow for extended drying times when painting in humid conditions or temperatures lower than 65 degrees.
- Work in lighter coats with less thinning and extended re-coat times.
- Allowing each light coat to dry tack free before applying next coat achieves quicker times to tape or clear.

#### Cleaning

- Use water to clean guns after use and to rinse in-between color changes.
- Soak gun and brush in 4008 Restorer after painting. 4008 helps partially remove dried paint for easy clean-up with soap & water.
- Do not use 4012 to clean.

### **Coverage**

- 300 sq. feet approximately per 1 gallon
- Brush & roller coverage is enhanced with addition of 4015 Cross-Linker.

### **Preparation**

Follow standard practices & procedures. If the surface has been damaged, remove all loose, chalking or flaking paint from the surface.

- Scenix SSR Clears are suitable for all direct to substrate applications except untreated metal. Prepare untreated metal with direct-to-metal primer or phosphoric acid.
- Adhesion promoter not required.
- Scenix SSR Clears have excellent adhesion direct to plastic, aluminum, fiberglass and other difficult to paint substrates.

### **High Performance Scenix Mix**

Mix any Scenix SSR Clear with Scenix Mural & Theme Paint to create a "High Performance" version for painting difficult to paint substrates such as plastic, fiberglass, and polyester; or in extreme conditions such as direct exposure to water, where maximum adhesion and durability is required.

Mix Scenix SSR Clear approximately 30% per total volume with Scenix for a paint that has a higher aliphatic resin load.

Note: 4015 Cross-Linker added to standard Scenix is exceptionally durable and cost-effective paint compared to High Performance Scenix. Testing first with Scenix activated with 4015 Cross-Linker is recommended.

### **Health & Safety**

Use in a well-ventilated area. Avoid contact with eyes. Wash hands thoroughly with soap and warm water after use. Do not ingest.

When spraying or sanding, use a properly-fitting NIOSH approved respirator per the manufacturer's instructions.

Skin contact: Thoroughly wash with soap and warm water before Scenix dries. Wearing gloves is recommended.

Eye contact: Rinse with clean water for 15 minutes. Seek medical attention.

Inhalation: Use in well ventilated areas and wear a NIOSH approved respirator.

Refer to Scenix SDS for additional information.

### **Warranty**

This product will perform as claimed if directions are followed. Warranty is limited to replacement or refund value of product. No other warranty is expressed or implied.

Manufactured by:



PO Box 120, 14 Airport Park Rd  
East Granby, CT 06026  
800.243.2712 | 860.653.5505  
info@createxcoldors.com

Available from:  
Dixie Art Airbrush  
[www.dixieart.com](http://www.dixieart.com)  
800-783-2612 - 504-836-0069